

WHAT THE FIX?!

Model:

ARONA (KJ7), CHZL
IBIZA V (KJ1), CHZL
POLO (AW1), CHZL

Fault symptoms:

- Rattling noise in the area of the engine.
- Loss of oil

SEAT

IBIZA V (KJ1, KJG); 1.0 TSI; kW: 70

ENGINE TIMING

Technical background:

- Screws for the cover for the exhaust camshaft adjuster are tightened with the wrong torque.

Potential fix:

Replace exhaust camshaft adjuster with sealing ring, cover and screws.

