

WHAT THE FIX?!

Model:

V90 II Cross Country (236)

Diesel engine;

V90 II Kombi (235)

Diesel engine

Fault symptoms:

The error message -AdBlue® dosage- is displayed in the instrument cluster.

VOLVO

V90 II Cross Country (236); D4 AWD; kW: 120

EXHAUST SYSTEM

Trouble code:

- P2BAF00 - Control unit faulty
- P2BAF09 - NOx system component faulty
- P204713 - Injection valve 1 for AdBlue®, 1st. cylinder bank Electric fault/interruption in circuit

Cause:

Wiring harness is rubbing against the right rear of the body.

Potential fix:

Check wiring harness at rear right in wheel housing, repair and reattach if necessary.

